M. A. R. 57 (Rule 116) **No. D**

Measurement Book

225112

Serial No. .....

Name of work Recon Structure & CC dvdy at 7th and 11th Cross Sooooording 11th A Cross road Bhuvaneshwari Nagar in ward No. 14 Bagalagunte

From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions		Depth	Contents	Reference to last Measurement
			Length	Breadth			
1	2	3	4	5	6	7	8
	Estimated Cost Rs	50.0 Lakhs					
	Head of AC :	PDW Budgeted Head P Code No 3316					
	Job code NO :	014-18-000067					
	work order NO :	~~Sooooooo~~ EE/DD/CO/38/2018-19					
	Adm Sanction NO	EE/DD/AS/623/2017-18. Dt					19.12.2017
	Technical Sanction NO	CE/DZ/TS/376/2017-18 Dt					20.12.2017
	Agency :	KRIDL, Bangalore					
	Bill NO :	First and Final			Dated :		

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Deck Slab for Culvert	1	17.0	1.60	0.25	6.80 m³	
	C&R	1	30	1.30	0.25	0.98 "	
					Total Qty	72.08 m³	
			@ 6594.96/m³			Rs	475314=00
SL NO 4	providing TMT Steel for Reinforcement Rce including Straightening cutting bending hooking placing as directed by Engineer						
	Qty vide page No 25187 of this MB						
					Qty	5.68 Tons	
			@ 64243.42/Tone			Rs	364903=00

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಆ ದಾಸನಪಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಪಶ್ಚಿಮಾಂಜಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

Serial No. 225118

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions		Depth	Contents	Reference to last Measurement
			Length	Breadth			
1	2	3	4	5	6	7	8
	At 7th A main Rd	1	50.0	5.0	=	250.0m²	
		1	50.0	5.0	=	250.0	
	At 8th A main Rd	1	6.0	5.0	=	30.0	
	8th B — 1st	1	34.0	3.3	=	112.20	
	7th main Road	1	78.0	3.90	=	304.20	
	cgbc 6/12/18	1	50.0	4.0	=	200.0	
		1	44.0	4.0	=	176.0	
				Total		1322.0m²	
	06/12/18			@	95.40/m²	Rs	126119=00
							4460127=00

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
							4460127 = 0
						11/1.	490614 = 0
							4950741 = 0

AE 06/12/18

06.12.2018

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶ್ರೀ ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

225119

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

Audited and admitted for Rs. 4950741=00

Passed by Cheque for Rs. 4404056=00

(..... .... - - .....

.... 546685=00

by adjustm

Accounts Superintendent

Exe. Engineer

B.B.M.P. Dasarahalli Division

Scanned by CamScanner